

### Locations along Capisic Brook (upstream to downstream)



Fig. 1. Pond above Evergreen Cemetery, 10/2003



Fig. 2. In Evergreen Cemetery (biological monitoring station S256), 4/2003



Fig. 3. Below confluence of main stem and northern branch, 7/2003



Fig. 4. Below Dennett Street crossing, 7/2003



Fig. 5. Below Brighton Avenue, 7/2003



Fig. 6. Below Lucas Street (biological monitoring station S257), 4/2003

## Selected Problem Conditions




Fig. 7. Stormflow conditions  
(below Lucas Street), 8/13/2004




Fig. 8. Baseflow conditions  
(below Lucas Street), 8/20/2004



Fig. 9. Combined Sewer Overflow  
below Evergreen Cemetery




Fig. 10. Channelization above  
Lucas Street



Fig. 11. Excessive algal growth  
in stream below Lucas Street  
(at S257, 7/2004)




Fig. 12. Dense residential  
development near stream